HAER ND, 5-KRAN, 1-E-

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

J. Clark Salyer National Wildlife Refuge, Dam 357

HAER No. ND-4-E

KRAMÉR VIC. Along the Souris River Bottineau County McHenry County North Dakota

NOTE: Photographs were taken by Frederick L. Quivik, photographer, May 1990

| ND-4-E-1 | VIEW OF DAM 357, SHOWING DOWNSTREAM FACE OF THE DAM, LOOKING WEST TOWARD THE OUTLET WORKS |
|-----------|--|
| ND-4-E-2 | VIEW OF DAM 357, SHOWING UPSTREAM FACE OF THE DAM, LOOKING WEST FROM THE NEW MINIMUM FLOW CONTROL STRUCTURE |
| ND-4-E-3 | VIEW OF DAM 357, LOOKING WEST ACROSS THE TOP OF THE OUTLET WORKS |
| ND-4-E-4 | VIEW OF DAM 357, SHOWING UPSTREAM SIDE OF OUTLET WORKS, LOOKING NORTHWEST |
| ND-4-E-5 | DETAIL VIEW OF UPSTREAM SIDE OF OUTLET WORKS, LOOKING NORTHWEST |
| ND-4-E-6 | VIEW OF DAM 357, LOOKING WEST ALONG THE CREST OF THE SPILLWAY FROM THE WEST END |
| ND-4-E-7 | VIEW OF WEST END OF THE SPILLWAY, DAM 357, SHOWING ORIGINAL FIELD-STONE WEIR WALL AND CONCRETE BUTTRESSING, LOOKING SOUTHWEST |
| ND-4-E-8 | VIEW OF UPSTREAM SIDE OF THE CONCRETE STOPLOG STRUCTURE NEAR THE MIDDLE OF THE SPILLWAY AT DAM 357, LOOKING SOUTHWEST |
| ND-4-E-9 | VIEW SHOWING UPSTREAM CONCRETE BULKHEAD FOR CONCRETE PIPE THROUGH THE DAM INSTALLED SHORTLY AFTER DAM 357 WAS COMPLETED, LOOKING NORTHEAST |
| ND-4-E-10 | VIEW OF MINIMUM FLOW CONTROL GATE STRUCTURE INSTALLED UPSTREAM FACE OF DAM 357 IN MID-1960s, LOOKING NORTHWEST |

The following are photocopies of historic photographs. Original prints can be found in narrative reports of the Lower Souris Migratory Waterfowl Refuge for the 1930s, on file at the headquarters of the J. Clark Salyer National Wildlife Refuge, Upham, North Dakota.

| ND-4-E-11 | VIEW OF C | ONSTRUCTION | WORK ON SPI | LLWAY WALI | L. DAM 357 |
|-----------|-----------|-------------|-------------|------------|------------|
|-----------|-----------|-------------|-------------|------------|------------|

ND-4-E-12 VIEW OF COMPLETED SPILLWAY WALL AT DAM 357

J. Clark Salyer National Wildlife Refuge, Dam 357HAER No. ND-4-EIndex to Photographs (Page 2)

| ND-4-E-13 | FINISHED RUBBLE MASONRY AT WEST END OF SPILLWAY, DAM 357 | | | |
|---|--|--|--|--|
| ND-4-E-14 | STOPLOG STRUCTURE, DAM 357 | | | |
| ND-4-E-15 | ROCK WORK ON APPROACH TO FLOOD GATES, DAM 357 | | | |
| ND-4-E-16 | DOWNSTREAM OF OUTLET WORKS AT DAM 357 | | | |
| ND-4-E-17 | UPSTREAM SIDE OF OUTLET WORKS AT DAM 357 | | | |
| ND-4-E-18 | DOWNSTREAM SIDE OF GATES AT DAM 357 | | | |
| ND-4-E-19 | UPSTREAM SIDE OF GATES AT DAM 357 | | | |
| The following are photographic copies of original construction drawings from files at the Office of the Chief Engineer, U.S. Fish and Wildlife Service Regional Office, Denver. | | | | |
| ND-4-E-20 | TOPOGRAPHIC MAP OF MARSH AREA NORTH OF DAM 357 March 1937 | | | |
| ND-4-E-21 | STRUCTURAL DETAILS FOR GATE, STRUCTURE NO. 357 June 26, 1936 | | | |
| ND-4-E-22 | STRUCTURAL DETAILS FOR SPILLWAY, STRUCTURE NO. 357 June 26, 1936 | | | |
| ND-4-E-23 | DETAILS FOR STOP LOG GATE AT DAM 357 May 1937 | | | |
| ND-4-E-24 | PLAN AND PROFILE, STRUCTURE NO. 357 | | | |

For photographs and historical information on other dams in the J. Clark Salyer National Wildlife Refuge, see HAER No. ND-4-A, Dam 320; HAER No. ND-4-B, Dam No. 326; HAER No. ND-4-C, Dam 332, and HAER No. ND-4-D, Dam 341.

PIPE & GATE OUTLET CONTROL AT DAM NO. 357

June 26, 1936

ND-4-E-25